

**STANDARD ARRIVAL ROUTES – INSTRUMENT
(STAR) UST-KAMENOGORSK RWY 12**

BANOV 3F

After crossing BANOV (R 028.7° D 43.0 UKM), proceed on track 209° to UKM.
Cross BANOV at FL120-FL140.

DEVNA 3F

After crossing DEVNA (R 076.8° D 42.6 UKM), proceed on track 257° to UKM.
Cross DEVNA at FL130-FL140.

ABOTO 3F

After crossing ABOTO (R 141.6° D 42.7 UKM), proceed on track 322° to UKM.
Cross ABOTO at FL120-FL140.

LASNA 3F

After crossing LASNA (R 207.8° D 43.3 UKM), proceed on track 028° to UKM.
Use LASNA 3F when UAR38 is not activated.
Cross LASNA at FL120-FL140.

NOKNA 3F

After crossing NOKNA (R 252.9° D 51.9 UKM), proceed on track 073° to UKM.
Cross NOKNA at 6000-FL140.

LIRNA 3F

After crossing LIRNA (R 276.9° D 45.2 UKM), proceed on track 097° to UKM.
Cross LIRNA at 6000-FL140.

ADARO 3F

After crossing ADARO (R 325.8° D 51.2 UKM), proceed on track 146° to UKM.
Cross ADARO at FL120-FL140.