

STANDARD ARRIVAL ROUTES – INSTRUMENT (STAR) TURKISTAN RWY 05
ARVAR 1A After crossing ARVAR (R076.8° D26.2 TRK) proceed on track 257° to TRK. Cross ARVAR at 7000 or above. Cross TRK at 6000.
MAGOL 1A After crossing MAGOL (R147.8° D28.7 TRK) proceed on track 328° to TRK. Cross MAGOL at 7000 or above. Cross TRK at 6000.
LARBA 1A After crossing LARBA (R169.9° D30.2 TRK) proceed on track 350° to TRK. Cross LARBA at 7000 or above. Cross TRK at 6000.
RELRU 1A After crossing RELRU (R195.6° D32.5 TRK) proceed on track 015° to TRK. Cross RELRU at 7000 or above. Cross TRK at 6000.
KARIM 1A After crossing KARIM (R250.9° D35.3 TRK) proceed on track 070° to TRK. Cross KARIM at 7000 or above. Cross TRK at 6000.
KUDUG 1A After crossing KUDUG (R287.5° D31.7 TRK) proceed on track 107° to TRK. Cross KUDUG at 7000 or above. Cross TRK at 6000.
GOBOR 1A After crossing GOBOR (R322.5° D21.8 TRK) proceed on track 142° to TRK. Cross GOBOR at 9000 or above. Cross TRK at 6000.